

General Information

- transparent repair patch for repairing tears and holes
- extremely strong and very elastic
- usable at temperature between -28 to +60°C (-18 to 140°F)
- **PVC Solution Tape (Type B):** repairs PVC
- **Multi Solution Tape (Type A):** repairs everything else (including metal)
- both versions can be bought as rolls of various sizes: 3.2cm, 7.6cm and 15.2cm (1.25", 3" and 6")



MST 100x3,2



MST 100x7,6



MST 100x15,2



PST 100x3,2



PST 100x7,6



PST 100x15,2

How do we handle it

- internal testing with HEYtex material: **product can be recommended** (test results: see next page)
- customers like Bieri offer the product as repair sets for their truck tarp customers
- we will **not offer the product in our assortment** but refer customers in need to the following provider:

Van der Kamp Multi Products

contact person: Henry van der Kamp

www.multi-solution-tape.com

info@multi-solution-tape.com

Tel. D: +49 (0)151 2814 8247

Tel. NL: +31 (0)316 247 786

Results of internal testing

Material: H5871-0286-LW Qualität: Rollenkarte: 111757	Auftraggeber: Kühling Boris Qualitätssicherung Textil Prüfdatum: 25.09.2017 Prüfer: Ender
Auftragsbeschreibung: Musteranalyse	

Parameter	H5871-0286-LW	H5871-0286-LW + RepairKit
Höchstzugkraft DIN EN ISO 1421 Kette/Schuss N/5cm	3364/3089	3285/3229
Höchstzugkraftdehnung DIN EN ISO 1421 Kette/Schuss %	20,1/27,4	20,8/25,8
Knickfestigkeit DIN 53359 Form A	100.000	100.000
Kältebeständigkeit DIN EN 495-5	-30°C	-30°C
Transluzenzmessung %	16,5	16,5
Wassersäule DIN EN 20811	2M	2M
Brennverhalten DIN 4102 B2	i.O	n.i.O

Kunde: Material: clipeum 650 EN lw Qualität: Rollenkarte: 1117572011 Einsatzgebiet:	Labor- Nr.: Auftraggeber: B. Kühling Qualitätssicherung Textil Prüfdatum: 25.10.2017 Prüfer: Torbecke
Auftragsbeschreibung: Prüfung Repair-Kit für HEYtent	

Haftungsprüfung geklebt

Temperatur	Prüfrichtung	Mittelw. Fmax N/5cm
Normklima	Kette	32
Normklima	Schuss	32
50°C	Kette	16
50°C	Schuss	16
75°C	Kette	10
75°C	Schuss	15

Bei der Messung der Haftwerte konnten nur wenige Werte gesammelt werden, da bei dem ablösen der Folie keine „Werte-Peaks“ entstanden sind und somit das Prüfprogramm keine Auswertung erstellen kann. Allerdings war es bei einigen Prüfungen möglich eine Auswertung zu erstellen.

How the tape works

